

Grease Trap & Oil/Water Separator Cleaning Contractors

Please keep in mind that the City of West St. Paul does not recommend one contractor over any other, this information is being provided as a service to you. This list is subject to change.

2020 - 2021

Contractor	Email/Website	Phone	Clean	Storage	Disposal
Alto Sewer Service	mike@altosewer.com	(651) 822-5345	✓		✓
DC Annis Sewer & Drain	office@cloggedplumbing.com	(651) 209-0275	✓		
Drain King Inc	drainkinginc.com	(763) 786-3000	✓		✓
Liquid Environmental Solutions	liquidenviro.com	(866) 694-7327	✓		✓
Marvel Sewer & Drain	ben@marvelseweranddrain.com	(763) 445-9005	✓		
McDonough's – St. Paul	info@unclogdrains.com	(651) 436-3370	✓		
Meyer Sewer Service	meyersewer.com/contact	(651) 450-0162	✓		
Midwest Grease	midwestgrease.com/contact	(855) 525-0205	✓	✓	✓
Mr. Rooter	tony@mrrootermn.com	(651) 341-5899	✓		
Restaurant Technologies Inc	rti-inc.com/connect	(651) 304-3169	✓	✓	✓
Rooterman	rooterman.com/schmidt	(888) 726-4629	✓		
Roto-Rooter	rotorooter.com/stpaul	(763) 519-3977	✓		
Sanimax	Sanimax.com	(612) 529-2492		✓	✓
Sewer Services Inc.	sewerpumpingservices.com	(952) 873-3292	✓		✓
Ultimate Drain Services	ultimateplj@gmail.com	(651) 436-4700	✓		

Grease trap or interceptor cleaning must be conducted a minimum of every thirty (30) days or more frequently if the unit has accumulated waste, accounting for 25% of its wetted depth, as measured from the water level to the interior tank bottom. The floating grease, liquids, sludge, and scrapings from the interceptor must all be removed. Under no circumstances may the waste hauler reintroduce the removed water or materials into the City's sanitary sewer system.